



m/003/026

STATE ACTION

Mail to:
 Grants Coordinator
 State Clearinghouse
 116 State Capitol
 Salt Lake City, Utah 84114
 Phone: (801) 538-1027 - Fax: (801) 538-1547 Fax


1. Administering State Agency: Division of Oil, Gas and Mining 1594 West North Temple Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801	2. State Application Identifier Numbers: (assigned by State Clearinghouse) 3. Approximate date project will start: Existing small mining (< 5 acre) operation that is being expanded to a large mining category.
4. Areawide clearinghouse(s) receiving State Action: Roger Jones, Executive Director Bear River Association of Governments 170 North Main, Room 2 Logan, Utah 84321	
5. Type of action: <input type="checkbox"/> Lease <input checked="" type="checkbox"/> Permit <input type="checkbox"/> License <input type="checkbox"/> Land Acquisition <input type="checkbox"/> Land Sale <input type="checkbox"/> Land Exchange <input type="checkbox"/> Other _____	
6. Title of proposed action: Star Stone Quarries, Inc., Rosebud Quarry - Large Mining Operation - M/003/026	
7. Description: <u>During Operations:</u> Salvageable soil over quarry and waste dump areas will be scraped from the surface using a D8 dozer or excavator bucket and piled up prior to mining. A hydraulic excavator is used to extract the stone from the quarry and distributed to workers on the quarry dump and pad to process. Stone is split by hand to uniform size and stacked on pallets for shipping. Unusable material is placed on the waste dumps. Quarry cuts will be approximately ten feet deep. Equipment used includes a D-8 bulldozer, hydraulic excavator, two-yard front end loader, and two dump trucks. A 500 gallon fuel tank is located on site within a secondary containment structure. <u>After Operations:</u> Excluding 0.2 acres of pre-existing access road, all disturbed areas will be reclaimed. Excess (waste rock) materials will be used to backfill quarry pit areas so that they are free-draining. The area will be regraded to approximate original contours (slopes of 3 horizontal to 1 vertical). Quarry and waste rock dump areas will be covered with 18 inches of fines (amended with compost to support vegetation). Salvaged soil will placed over the fines prior to seeding. All areas will be seeded by broadcasting an approved seed mix designed to meet the intended post mining land use of grazing and wildlife habitat.	
8. Land affected (site location map required) (indicate county) SW1/4 NW1/4 and the SE1/4 SW1/4 of Section 14, Township 10 North, Range 16 West, SLBM, Box Elder County, Utah	
9. Has the local government(s) been contacted? Yes - With a copy of the public notice	
10. Possible significant impacts likely to occur: None	
11. Name and phone number of district representative from your agency near project site, if applicable: N/A	
12. For further information, contact: Lynn Kunzler, Senior Reclamation Specialist Phone: (801) 538-5310	13. Signature and title of authorized officer: <div style="text-align: center;">  Permit Supervisor </div> Date: July 7, 2000


MINE SITE LOCATION MAP



Division of Oil, Gas and Mining

July 10, 2000





Emigrant Pass/Scale 1:62,500 1 cm = 3.1 km

Tion River
Section 14
Emigrant Pass Quad
Rosebud mine

EMIGRANT PASS QUADRANGLE
UTAH-BOX ELDER CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)

2887 II NW
(POTTERS CREEK)

40° 28'

1:410,000 FEET

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

324

325

326

327

328

329

330

331

332

333

334

335

336

337

338

339

340

341

342

343

344

345

346

347

348

349

350

351


352

353

354

355

3



T 10 N R 16 W
 Section 14
 Emigrant Pass Quad

ROSEBUD QUARRY
STAR STONE QUARRIES, INC.
 Map # 1.1
 Property Boundaries of Surface Ownership
 Streams Affected by Operation

RECEIVED

MAR 13 2000

DIVISION OF
 OIL, GAS AND MINING